## Kapsch TrafficCom



SERVICE BULLETIN		# 17-001 (YY-###)
The purpose of a Service Bulletin is to communicate issues that have been identified as requiring field action		
SECTION A		
23231-015	Date: (mm-dd-yyyy)	11/16/2017
irculators used with MPR2 and IPR2.3 Readers	Serial #(s):	N/A
ected Revision:  All Revisions		
ffected Location(s):  All Locations		
Description of Issue – ( <i>Include digital image(s) of issue, where applicable</i> ):  The JANUS MPR2 and MPR 2.3 Readers make use of an external Circulator mounted either at the antenna or in the reader cabinet. External Circulators, mounted at the antenna without proper protection, may, after prolonged exposure to environmental conditions, deteriorate due to water ingress causing degraded transponder capture performance.		
SECTION B		
Actions Required to Mitigate the Issue  All external Circulators not mounted inside a weatherproof cabinet shall be installed in accordance with Kapsch Service Procedure FSP-006, attached. This procedure involves wrapping the Circulator and its mating connections with a Self-amalgamating tape to prevent water ingress.		
	SECTION A  23231-015  irculators used with MPR2 and PR2.3 Readers  Il Revisions  Il Locations  age(s) of issue, where applicable):  ders make use of an external Circulator nounted at the antenna without proper protected due to water ingress causing degraded.  SECTION B  expected as weatherproof cabinet shall be in this procedure involves wrapping the	SECTION A  Date: (mm-dd-yyyy)  irculators used with MPR2 and PR2.3 Readers  Il Locations Il Locations Ige(s) of issue, where applicable):  ders make use of an external Circulator mounted either anounted at the antenna without proper protection, may, aftite due to water ingress causing degraded transponder calculations  SECTION B  SECTION B  SECTION B  SECTION B

Name of Issuer: Ed Rolo

All customers using MPR2 and MPR 2.3 readers

Distribution List: